

Locational Convergence Plan for the Year 2018-19-----District KARGIL

| S.No | batch | Project | Name of activities | Latitude | Longitude | Location of activities | | | | Nature of activity | Tentative Estimated cost (lakhs) convergen | Rs. In Lacs | |
|----------------|-------|---------|------------------------------------|-------------|-------------|------------------------|----------------|----------------|--------------|--------------------|--------------------------------------------|------------------|---------------------|
| | | | | | | Village | panchayat | block | constituency | | | Labour Cost @60% | Material Cost @ 40% |
| 1 | III | IWMP-I | Water storage tank at Lamsu kalung | 34.5222878 | 76.3755018 | Lamsu | Youqma kharboo | Shakar-chiktan | kargil | NRM | 1 | 0.3348 | 0.6652 |
| 2 | III | IWMP-I | Dry bund sandoo-I | 34.5439882 | 76.398389 | sandoo | Youqma kharboo | Shakar-chiktan | kargil | NRM | 1 | 0.3348 | 0.6652 |
| 3 | III | IWMP-I | Dry bund sandoo-II | 34.5439885 | 76.398387 | sandoo | Youqma kharboo | Shakar-chiktan | kargil | NRM | 1 | 0.3348 | 0.6652 |
| 4 | III | IWMP-I | Dry bund sandoo-III | 34.5439882 | 76.398389 | sandoo | Youqma kharboo | Shakar-chiktan | kargil | NRM | 1 | 0.3348 | 0.6652 |
| 5 | III | IWMP-I | Dry bund sandoo-III | 34.5439882 | 76.398389 | sandoo | Youqma kharboo | Shakar-chiktan | kargil | NRM | 1 | 0.3348 | 0.6652 |
| 6 | III | IWMP-I | Dry bund sandoo lungma | 34.54411 | 76.39845 | sandoo | Youqma kharboo | Shakar-chiktan | kargil | NRM | 1 | 0.3348 | 0.6652 |
| 7 | III | IWMP-I | Dry bund sandoo kalung | 34.53271 | 76.3982 | sandoo | Youqma kharboo | Shakar-chiktan | kargil | NRM | 1 | 0.3348 | 0.6652 |
| 8 | III | IWMP-I | Water storage tank Lamsu lungma-I | 34.52102 | 76.37567 | Lamsu | Youqma kharboo | Shakar-chiktan | kargil | NRM | 3.5 | 1.209 | 2.291 |
| 9 | III | IWMP-I | Water storage tank Lamsu-II | 34 31 15.48 | 76 22 30.52 | Lamsu | Youqma kharboo | Shakar-chiktan | kargil | NRM | 3.5 | 1.209 | 2.291 |
| 10 | III | IWMP-I | Water storage tank Lamsu-III | 34 31 15.48 | 76 22 30.52 | Lamsu | Youqma kharboo | Shakar-chiktan | kargil | NRM | 3.5 | 1.209 | 2.291 |
| 11 | III | IWMP-I | Snow check dam halalfafsa-IV | 34.45222 | 76.37667 | shakar | shakar | Shakar-chiktan | kargil | NRM | 3.5 | 1.209 | 2.291 |
| 12 | III | IWMP-I | Snow check dam halalfafsa-V | 34.45139 | 76.37694 | shakar | shakar | Shakar-chiktan | kargil | NRM | 3.5 | 1.209 | 2.291 |
| 13 | III | IWMP-I | Snow check dam halalfafsa-VI | 34.45139 | 76.37694 | shakar | shakar | Shakar-chiktan | kargil | NRM | 3.5 | 1.209 | 2.291 |
| 14 | III | IWMP-I | Field channel at sandoo-III | 34.53704 | 76.39988 | sandoo | Youqma kharboo | Shakar-chiktan | kargil | NRM | 2.5 | 1.063 | 1.436 |
| 15 | III | IWMP-I | Field channel at sandoo-IV | 34 32 10.47 | 76 24 01.68 | sandoo | Youqma kharboo | Shakar-chiktan | kargil | NRM | 2.5 | 1.063 | 1.436 |
| IWMP-II | | | | | | | | | | | | | |

| | | | | | | | | | | | | | |
|-----------------|-----|----------|------------------------------------------------------|------------|------------|-----------|----------|----------------|--------|-----|------|--------|--------|
| 1 | III | IWMP-II | Irrigation channel at Tsaraks | 34.37415 | 76.48735 | Khangral | Chiktan | Shakar-chiktan | Kargil | NRM | 3.59 | 1.305 | 2.284 |
| 2 | III | IWMP-II | Protection wall at Khangral | 34.37415 | 76.48752 | Khangral | Chiktan | Shakar-chiktan | Kargil | NRM | 3.6 | 1.305 | 2.294 |
| 3 | III | IWMP-II | Water harvesting structure kull at tsaraks | 34.37415 | 76.48731 | Tsarks | Chiktan | Shakar-chiktan | Kargil | NRM | 3 | 1.116 | 1.884 |
| 4 | III | IWMP-II | Protection / retaining wall at khangral-I (32 m | 34.2124.50 | 76.3236.01 | khangral | Chiktan | Shakar-chiktan | Kargil | NRM | 1.77 | 0.654 | 1.115 |
| 5 | III | IWMP-II | Construction of R/wall Gayour Kull at stakcha | 34.349949 | 76.552288 | Stakchay | Khangral | Shakar-chiktan | Kargil | NRM | 2 | 0.6957 | 1.3025 |
| 6 | III | IWMP-II | Construction of R/wall Gayour Kull at stakcha | 34.349949 | 76.552288 | Stakchay | Khangral | Shakar-chiktan | Kargil | NRM | 2 | 0.6957 | 1.3025 |
| 7 | III | IWMP-II | Construction of R/wall Gayour Kull at gomorju | 34.349709 | 76.55193 | Gomorjuk | Chiktan | Shakar-chiktan | Kargil | NRM | 2 | 0.6957 | 1.3025 |
| 8 | III | IWMP-II | Irrigation kull at chong chong Doo. | 3.385308 | 76.524798 | Khangral | Chiktan | Shakar-chiktan | Kargil | NRM | 5 | 2.157 | 2.842 |
| 9 | III | IWMP-II | Crate bund samrah lungma 50 Numbers | 34.2434.86 | 76.3352.75 | khangral | Chiktan | Shakar-chiktan | Kargil | NRM | 5 | 2.157 | 2.842 |
| 10 | III | IWMP-II | Crate bund samrah lungma 50 Numbers | 34.40889 | 76.3352.75 | Samrah | Samrah | Shakar-chiktan | Kargil | NRM | 5 | 2.157 | 2.842 |
| 11 | III | IWMP-II | Water reservoir tank Pargue-I | 34.420824 | 76.514896 | Samrah | Pargue | Shakar-chiktan | Kargil | NRM | 5 | 2.157 | 2.842 |
| 12 | III | IWMP-II | Water reservoir tank Pargue-II | 34.420824 | 76.514896 | Samrah | Pargue | Shakar-chiktan | Kargil | NRM | 5 | 2.157 | 2.842 |
| 13 | III | IWMP-II | Irrigation channel chulichan-V | 34.2533.80 | 76.3121.15 | Chulichan | Chiktan | Shakar-chiktan | Kargil | NRM | 4.6 | 1.78 | 2.819 |
| 14 | III | IWMP-II | Irrigation channel chulichan-VI | 34.2533.80 | 76.3121.15 | Chulichan | Chiktan | Shakar-chiktan | Kargil | NRM | 4.6 | 1.78 | 2.819 |
| 15 | III | IWMP-II | Water reservoir tan Sarbartan | 34.414749 | 76.53252 | Samrah | Chiktan | Shakar-chiktan | Kargil | NRM | 5 | 2.157 | 2.842 |
| 16 | III | IWMP-II | Land development Part- II | 34.411433 | 76.526146 | Samrah | Chiktan | Shakar-chiktan | Kargil | NRM | 5 | 2.157 | 2.842 |
| IWMP-III | | | | | | | | | | | | | |
| 1 | IV | IWMP-III | Renovation of water reservoir tank at Murad Bagh.-I | 34.2600.49 | 75.4227.32 | M-Bagh | Holial | Drass | Kargil | NRM | 5 | 2.157 | 2.842 |
| 2 | IV | IWMP-III | Renovation of water reservoir tank at Murad Bagh.II | 34.2553.81 | 75.4238.37 | M-Bagh | Holial | Drass | Kargil | NRM | 4 | 1.51 | 2.489 |
| 3 | IV | IWMP-III | Renovation of water reservoir tank at Murad Bagh.III | 34.2553.81 | 75.4238.37 | M-Bagh | Holial | Drass | Kargil | NRM | 4 | 1.51 | 2.489 |

| | | | | | | | | | | | | | |
|----------------|----|----------|-----------------------------------------------------|-------------|-------------|---------|---------|-------|--------|-----|------|--------|--------|
| 4 | IV | IWMP-III | Renovation of water reservoir tank at Murad Bagh.VI | 34 25 53.81 | 75 42 38.37 | M-Bagh | Holial | Drass | Kargil | NRM | 5 | 2.157 | 2.842 |
| 5 | IV | IWMP-III | Nallah Bund at Mursd bagh-I | 34 25 51.09 | 75 42 18.93 | M-bagh | Holial | Drass | Kargil | NRM | 5 | 2.157 | 2.842 |
| 6 | IV | IWMP-III | Nallah Bund at Mursd bagh.II | 34 25 51.09 | 75 42 18.93 | M-bagh | Holial | Drass | Kargil | NRM | 5 | 2.157 | 2.842 |
| 7 | IV | IWMP-III | Renovation of water reservoir tank at Holial.I | 34 25 50.08 | 75 42 39.56 | Holial | Holial | Drass | Kargil | NRM | 5 | 2.157 | 2.842 |
| 8 | IV | IWMP-III | Renovation of water reservoir tank at Holial.II | 34 25 50.08 | 75 42 39.56 | Holial | Holial | Drass | Kargil | NRM | 5 | 2.157 | 2.842 |
| 9 | IV | IWMP-III | Renovation of irrigation channel at holial. | 34 26 03.19 | 75 43 34.89 | Holial | Holial | Drass | Kargil | NRM | 3.38 | 1.023 | 2.357 |
| 10 | IV | IWMP-III | Nallah Bund at Holial part-I. | 34 26 01.35 | 75 43 24.88 | Holial | Holial | Drass | Kargil | NRM | 3 | 1.116 | 1.884 |
| 11 | IV | IWMP-III | Nallah Bund at Holial part-II. | 34 26 01.75 | 75 43 20.57 | Holial | Holial | Drass | Kargil | NRM | 3 | 1.116 | 1.884 |
| IWMP-IV | | | | | | | | | | | 0 | 0 | 0 |
| 1 | V | IWMP-IV | Irrigation channel bhimbat-Ningur | 34.434665 | 75.819034 | Bhimbat | bhimbat | drass | Kargil | NRM | 4 | 1.51 | 2.489 |
| 2 | V | IWMP-IV | Irrigation channel bhimbat-Kutyal | 34 26 14.29 | 75 49 10.60 | Bhimbat | bhimbat | drass | Kargil | NRM | 4 | 1.51 | 2.489 |
| 3 | V | IWMP-IV | Irrigation channel bhimbat | 34 26 15.73 | 75 49 10.97 | Bhimbat | bhimbat | drass | Kargil | NRM | 4 | 1.51 | 2.489 |
| 4 | V | IWMP-IV | Head Work bhimbat-I | 34.434974 | 75.818955 | Bhimbat | bhimbat | drass | Kargil | NRM | 5 | 2.157 | 2.842 |
| 5 | V | IWMP-IV | Head Work bhimbat-II | 34.434974 | 75.818955 | Bhimbat | bhimbat | drass | Kargil | NRM | 5 | 2.157 | 2.842 |
| 6 | V | IWMP-IV | Head Work bhimbat-III | 34.434974 | 75.818955 | Bhimbat | bhimbat | drass | Kargil | NRM | 5 | 2.157 | 2.842 |
| 7 | V | IWMP-IV | Head Work bhimbat-IV | 34.434974 | 75.818955 | Bhimbat | bhimbat | drass | Kargil | NRM | 5 | 2.157 | 2.842 |
| 8 | V | IWMP-IV | Protection bund at amin bag kull-I | 34.441576 | 75.821153 | Bhimbat | bhimbat | drass | Kargil | NRM | 4 | 1.5103 | 2.4896 |
| 9 | V | IWMP-IV | Protection bund at amin bag kull-I | 34.43959 | 75.819622 | Bhimbat | bhimbat | drass | Kargil | NRM | 4 | 1.5103 | 2.4896 |
| IWMP-V | | | | | | | | | | | 0 | 0 | 0 |
| 1 | V | IWMP-V | Land development Part-I | 34.57671 | 75.97497 | kaksar | kaksar | Drass | kargil | NRM | 4 | 1.51 | 2.489 |

| | | | | | | | | | | | | | |
|----------------|---|---------|----------------------------------|-------------|-------------|--------|--------|-------|--------|-----|------|--------|--------|
| 2 | V | IWMP-V | Land development Part-II | 34 34 45.87 | 75 85 33.94 | kaksar | kaksar | Drass | kargil | NRM | 3 | 1.116 | 1.884 |
| 3 | V | IWMP-V | Land development Part-III | 34 34 45.87 | 75 85 35.29 | kaksar | kaksar | Drass | kargil | NRM | 3 | 1.116 | 1.884 |
| 4 | V | IWMP-V | Land development Part-IV | 34 34 43.03 | 75 58 37.91 | kaksar | kaksar | Drass | kargil | NRM | 2.44 | 0.9 | 1.539 |
| 6 | V | IWMP-V | Land development Part-V | 34 34 43.03 | 75 58 37.91 | kaksar | kaksar | Drass | kargil | NRM | 3 | 1.116 | 1.884 |
| 7 | V | IWMP-V | Land development Part-Vi | 34 34 45.87 | 75 85 33.94 | kaksar | kaksar | Drass | kargil | NRM | 4 | 1.5103 | 2.4896 |
| 8 | V | IWMP-V | Land development Part-VII | 34 34 43.03 | 75 58 37.91 | kaksar | kaksar | Drass | kargil | NRM | 4 | 1.5103 | 2.4896 |
| 9 | V | IWMP-V | Land development Part-VIII | 34 34 45.82 | 75 85 35.28 | kaksar | kaksar | Drass | kargil | NRM | 5 | 2.157 | 2.842 |
| 10 | V | IWMP-V | Land development Part-IX | 34 34 45.81 | 75 85 35.27 | kaksar | kaksar | Drass | kargil | NRM | 5 | 2.157 | 2.842 |
| 11 | V | IWMP-V | Land development Part-X | 34 34 45.84 | 75 85 35.26 | kaksar | kaksar | Drass | kargil | NRM | 4 | 1.5103 | 2.4896 |
| IWMP-VI | | | | | | | | | | | | | |
| 1 | V | IWMP-VI | Irrigation channel at Goshan-I | 34.44494 | 75.75396 | Goshan | Goshan | drass | kargil | NRM | 2.3 | 0.99 | 1.3997 |
| 2 | V | IWMP-VI | Irrigation channel at Goshan-II | 34 26 40.69 | 75 45 13.38 | Goshan | Goshan | drass | kargil | NRM | 3 | 1.116 | 1.884 |
| 3 | V | IWMP-VI | Irrigation channel at Goshan-III | 34 26 40.65 | 75 45 14.68 | Goshan | Goshan | drass | kargil | NRM | 2.88 | 1.021 | 1.853 |
| 4 | V | IWMP-VI | Irrigation channel at Goshan-IV | 34 26 39.58 | 75 45 13.95 | Goshan | Goshan | drass | kargil | NRM | 3.48 | 1.209 | 2.271 |
| 5 | V | IWMP-VI | Supper Passage at Goshan | 34.44598 | 75.755969 | Goshan | Goshan | drass | kargil | NRM | 2 | 0.6957 | 1.3025 |

Project manager

IWMP-Kargil